

### Attachment 3 - Photos of Kinloch Lodge



N Elevation preparation for new piles



Substantial timbering for seismic bracing



Original 1870 chimney  
Foundation (Large rocks!)



Reinforcing cage and  
ties for concrete



2023 concrete slab foundation  
ready for pouring



1870 totara piles, rotted and unbraced



2023 piles with substantially engineered  
bracing